



## SPACESHIPS UK - DAMAGE PRICE LIST

Prices in GBP and include VAT

Price are subject to change

Loss of use charges will be charged at the daily rate shown on the rental agreement. Minimum 1 day; maximum 30 days

This is not an extensive list of all potential damages. Serious damages will be assessed on a case-by-case basis

AREA	ITEM	DAMAGE TYPE	VOYAGER	MOTORHOME
<b>FRONT</b>				
	BONNET	SCUFF/SCRATCH SMALL < 100 mm	300	300
		SCUFF/SCRATCH MEDIUM(100-150 mm)	384	384
		SCUFF/SCRATCH LARGE( OVER 150 mm)	588	588
		DENT (UP TO 30 mm, NO PAINT DAMAGE)	114	114
		DENT SMALL( UP TO 80 mm)	300	300
		DENT MEDIUM(80-160 mm)	396	396
		DENT LARGE( OVER 160 mm)	588	588
	BUMPER	PLASTIC GRILLS	216	N/A
		SCUFF/SCRATCH SMALL < 100 mm	300	300
		SCUFF/SCRATCH MEDIUM(100-150 mm)	384	384
		SCUFF/SCRATCH LARGE( OVER 150 mm)	462	462
		DENT (UP TO 30 mm, NO PAINT DAMAGE)	114	114
		DENT SMALL( UP TO 80 mm)	300	300
		DENT MEDIUM(80-160 mm)	384	384
		DENT LARGE( OVER 160 mm)	462	462
		FOG LIGHT	132	N/A
	FRONT WING	SCUFF/SCRATCH SMALL < 100 mm	300	300
	Left or Right	SCUFF/SCRATCH MEDIUM(100-150 mm)	384	384
		SCUFF/SCRATCH LARGE( OVER 150 mm)	462	462
		DENT SMALL( UP TO 80 mm)	300	300
		DENT MEDIUM(80-160 mm)	384	384
		DENT LARGE( OVER 160 mm)	462	462
		DENT (UP TO 30 mm, NO PAINT DAMAGE)	114	114
	HEADLIGHT	CRACK/SCUFF/SCRATCH	324	324
	(LEFT OR RIGHT)	BROKEN HOUSING/MOUNTS	324	324
	NUMBERPLATE	DAMAGED/SCUFFED/CHIPPED	42	42
<b>SIDES</b>				
	FRONT DOOR	SCUFF/SCRATCH SMALL < 100 mm	300	300
	Left or Right	SCUFF/SCRATCH MEDIUM(100-150 mm)	384	384
		SCUFF/SCRATCH LARGE( OVER 150 mm)	462	462
		DAMAGE DUE TO OVER OPENING BY WIND	588	588
		DENT SMALL (UP TO 30 mm, NO PAINT DAMAGE)	114	114
		DENT SMALL( UP TO 80 mm)	300	300
		DENT MEDIUM(80-160 mm)	384	384
		DENT LARGE( OVER 160 mm)	462	462
	SLIDING DOOR	SCUFF/SCRATCH SMALL < 100 mm	300	N/A
	Left or Right	SCUFF/SCRATCH MEDIUM(100-150 mm)	384	N/A

		SCUFF/SCRATCH LARGE( OVER 150 mm)	462	N/A
		DENT SMALL (UP TO 30 mm, NO PAINT DAMAGE)	114	N/A
		DENT SMALL( UP TO 80 mm)	300	N/A
		DENT MEDIUM(80-160 mm)	384	N/A
		DENT LARGE( OVER 160 mm)	462	N/A
	MIRROR	SCUFF ON PAINTED HOUSING UNDER 100 mm	132	N/A
	Left or Right	CAMPERVAN - BROKEN GLASS ONLY	90	N/A
		MOTORHOME - BROKEN GLASS ONLY - SMALL	N/A	44
		MOTORHOME - BROKEN GLASS ONLY - LARGE	N/A	66
		SIDE REPEATER ONLY	42	66
		BROKEN HOUSING/BASE = REPLACEMENT MIRROR	300	366
	REAR QUARTER PANEL	SCUFF/SCRATCH SMALL < 100 mm	300	300
		SCUFF/SCRATCH MEDIUM(100-150 mm)	384	384
		SCUFF/SCRATCH LARGE( OVER 150 mm)	462	462
		DENT SMALL (UP TO 30 mm, NO PAINT DAMAGE)	114	114
		DENT SMALL( UP TO 80 mm)	300	300
		DENT MEDIUM(80-160 mm)	384	384
		DENT LARGE( OVER 160 mm)	462	462
	WHEEL ARCH	WHEEL ARCH TRIM	N/A	264
	CAB CORNER	CAB CORNER PANEL	N/A	594
	SIDE MARKER	SIDE MARKER TOP	N/A	42
		SIDE MARKER BOTTOM	N/A	42
	SILL	SCUFF/SCRATCH SMALL < 100 mm	348	N/A
	Left or Right	SCUFF/SCRATCH MEDIUM(100-150 mm)	408	N/A
		SCUFF/SCRATCH LARGE( OVER 150 mm)	540	N/A
		DENT SMALL (UP TO 30 mm, NO PAINT DAMAGE)	114	N/A
		DENT SMALL( UP TO 80 mm)	348	N/A
		DENT MEDIUM(80-160 mm)	480	N/A
		DENT LARGE( OVER 160 mm)	660	N/A
	MH DOORS	GAS LOCKER DOOR	N/A	354
		GAS LOCKER DOOR FRAME	N/A	258
		HABITATION DOOR	N/A	834
		HABITATION DOOR FRAME	N/A	474
		TOILET OUTSIDE SERVICE FLAP	N/A	258
<b>BACK</b>				
	REAR	SCUFF/SCRATCH SMALL < 100 mm	300	300
		SCUFF/SCRATCH MEDIUM(100-150 mm)	384	384
		SCUFF/SCRATCH LARGE( OVER 150 mm)	462	462
		DENT SMALL (UP TO 30 mm, NO PAINT DAMAGE)	114	114
		DENT SMALL( UP TO 80 mm)	300	300
		DENT MEDIUM(80-160 mm)	384	384
		DENT LARGE( OVER 160 mm)	462	462
	REAR BUMPER	SCUFF/SCRATCH SMALL < 100 mm	300	348
		SCUFF/SCRATCH MEDIUM(100-150 mm)	384	384
		SCUFF/SCRATCH LARGE( OVER 150 mm)	462	462
		DENT SMALL( UP TO 80 mm)	300	300
		DENT MEDIUM(80-160 mm)	384	384
		DENT LARGE( OVER 160 mm)	462	462
		BUMPER CORNER DAMAGE ONLY( L or R)	N/A	210
		CRACK SMALL (UP TO 100 mm)	384	420

		CRACK MEDIUM (100-150 mm)	432	528
		CRACK LARGE (OVER 150 mm)	528	612
<b>WINDOWS</b>				
	WINDSCREEN	CHIP UNDER 25 mm	36	36
		CRACKED	444	252
	VEHICLE WINDOW	TRIANGLE SHAPE	168	180
		DOOR WINDOW (L/R)	204	210
		SLIDING DOOR WINDOW (L/R/)	252	N/A
		REAR QUARTER SIDE WINDOW (L/R)	534	N/A
		TAILGATE WINDOW	570	N/A
		REAR LEFT DOOR	210	N/A
		REAR RIGHT DOOR	210	N/A
	MOTORHOME WINDOW	LARGE SIDE WINDOW	N/A	590
		OVERCAB SIDE WINDOW	N/A	395
		MEDIUM SIDE WINDOW	N/A	540
		BACK WINDOW	N/A	495
		SKYLIGHT GLASS	N/A	195
		SKYLIGHT COMPLETE	N/A	315
		OVERCAB PANORAMIC WINDOW	N/A	445
		WINDOW STRUT	N/A	55
<b>OTHER</b>				
	OUTSIDE	DAMAGE OVER 1.8M HIGH	N/A	INDIVIDUAL
		TV AERIAL	N/A	252
<b>TYRES</b>		TYRE REPLACEMENT	114	126
<b>INTERIOR</b>		COOKING KIT REPLACEMENT	150	240
		FRIDGE DOOR HANDLE	45	45
		BURNT FLOOR	120	N/A
		MISSING AWNING	300	N/A
		MISSING AWNING POLE	24	N/A
		MISSING/BURNT MATTRESSES	300	504
		BURNT SEATS	540	540
		TABLE( CRACK)	N/A	360
		BUNK BED DAMAGE	N/A	From 295
		HOB SAFETY GLASS	N/A	320
		OVEN SAFETY GLASS	N/A	315
<b>CLEANING</b>		EXCESSIVELY DIRTY/STAINED MATTRESS	90/mattress	90/mattress
		TOILETTE CASSETTE DIRTY/NOT EMPTY	N/A	200
		EXCESSIVELY DIRTY VEHICLE CLEANING FEE	100	200