



SPACESHIPS UK - DAMAGE PRICE LIST 2020

Prices in GBP and include VAT

Price are subject to change

Loss of use charges will be charged at the daily rate shown on the rental agreement. Minimum 1 day; maximum 30 days

This is not an extensive list of all potential damages. Serious damages will be assessed on a case-by-case basis

AREA	ITEM	DAMAGE TYPE	VEHICLE TYPE			
			CAMPER CAR	DELTA	VOYAGER	MOTORHOME
FRONT						
	BONNET	SCUFF/SCRATCH SMALL < 100 mm	264	288	300	300
		SCUFF/SCRATCH MEDIUM(100-150 mm)	354	372	384	384
		SCUFF/SCRATCH LARGE(OVER 150 mm)	540	564	588	588
		DENT (UP TO 30 mm, NO PAINT DAMAGE)	114	114	114	114
		DENT SMALL(UP TO 80 mm)	264	288	300	300
		DENT MEDIUM(80-160 mm)	366	384	396	396
		DENT LARGE(OVER 160 mm)	540	564	588	588
	BUMPER	PLASTIC GRILLS	156	180	216	N/A
		SCUFF/SCRATCH SMALL < 100 mm	264	288	300	300
		SCUFF/SCRATCH MEDIUM(100-150 mm)	354	372	384	384
		SCUFF/SCRATCH LARGE(OVER 150 mm)	420	444	462	462
		DENT (UP TO 30 mm, NO PAINT DAMAGE)	114	114	114	114
		DENT SMALL(UP TO 80 mm)	264	288	300	300
		DENT MEDIUM(80-160 mm)	354	372	384	384
		DENT LARGE(OVER 160 mm)	420	444	462	462
		FOG LIGHT	108	108	132	N/A
	FRONT WING	SCUFF/SCRATCH SMALL < 100 mm	264	288	300	300
	Left or Right	SCUFF/SCRATCH MEDIUM(100-150 mm)	354	372	384	384
		SCUFF/SCRATCH LARGE(OVER 150 mm)	420	444	462	462
		DENT SMALL(UP TO 80 mm)	264	288	300	300
		DENT MEDIUM(80-160 mm)	354	372	384	384
		DENT LARGE(OVER 160 mm)	420	444	462	462
		DENT (UP TO 30 mm, NO PAINT DAMAGE)	114	114	114	114
	HEADLIGHT	CRACK/SCUFF/SCRATCH	276	276	324	324
	(LEFT OR RIGHT)	BROKEN HOUSING/MOUNTS	276	276	324	324
	NUMBERPLATE	DAMAGED/SCUFFED/CHIPPED	42	42	42	42
SIDES						
	FRONT DOOR	SCUFF/SCRATCH SMALL < 100 mm	264	288	300	300
	Left or Right	SCUFF/SCRATCH MEDIUM(100-150 mm)	354	372	384	384
		SCUFF/SCRATCH LARGE(OVER 150 mm)	420	444	462	462
		DAMAGE DUE TO OVER OPENING BY WIND	540	540	588	588
		DENT SMALL (UP TO 30 mm, NO PAINT DAMAGE)	114	114	114	114
		DENT SMALL(UP TO 80 mm)	264	288	300	300
		DENT MEDIUM(80-160 mm)	354	372	384	384
		DENT LARGE(OVER 160 mm)	420	444	462	462
	SLIDING DOOR	SCUFF/SCRATCH SMALL < 100 mm	264	288	300	300
	Left or Right	SCUFF/SCRATCH MEDIUM(100-150 mm)	354	372	384	384
		SCUFF/SCRATCH LARGE(OVER 150 mm)	420	444	462	462
		DENT SMALL (UP TO 30 mm, NO PAINT DAMAGE)	114	114	114	114
		DENT SMALL(UP TO 80 mm)	264	288	300	300
		DENT MEDIUM(80-160 mm)	354	372	384	384
		DENT LARGE(OVER 160 mm)	420	444	462	462

	MIRROR	SCUFF ON PAINTED HOUSING UNDER 100 mm	132	144	132	N/A
	Left or Right	BROKEN GLASS ONLY	66	90	90	114
		BROKEN HOUSING/BASE = REPLACEMENT MIRROR	234	270	300	366
		SIDE REPEATER ONLY	N/A	N/A	42	66
	REAR QUARTER PANEL	SCUFF/SCRATCH SMALL < 100 mm	264	288	300	300
		SCUFF/SCRATCH MEDIUM(100-150 mm)	354	372	384	384
		SCUFF/SCRATCH LARGE(OVER 150 mm)	420	444	462	462
		DENT SMALL (UP TO 30 mm, NO PAINT DAMAGE)	114	114	114	114
		DENT SMALL(UP TO 80 mm)	264	288	300	300
		DENT MEDIUM(80-160 mm)	354	372	384	384
		DENT LARGE(OVER 160 mm)	420	444	462	462
	SILL	SCUFF/SCRATCH SMALL < 100 mm	264	288	348	N/A
	Left or Right	SCUFF/SCRATCH MEDIUM(100-150 mm)	312	336	408	N/A
		SCUFF/SCRATCH LARGE(OVER 150 mm)	420	456	540	N/A
		DENT SMALL (UP TO 30 mm, NO PAINT DAMAGE)	114	114	114	N/A
		DENT SMALL(UP TO 80 mm)	264	288	348	N/A
		DENT MEDIUM(80-160 mm)	408	444	480	N/A
		DENT LARGE(OVER 160 mm)	528	588	660	N/A
	BACK					
	REAR BARN DOOR	SCUFF/SCRATCH SMALL < 100 mm	264	N/A	300	300
	Left OR Right	SCUFF/SCRATCH MEDIUM(100-150 mm)	354	N/A	384	384
	incl Garage door on	SCUFF/SCRATCH LARGE(OVER 150 mm)	420	N/A	462	462
	motorhomes IF	DENT SMALL (UP TO 30 mm, NO PAINT DAMAGE)	114	N/A	114	114
	REPLACEMENT NOT	DENT SMALL(UP TO 80 mm)	264	N/A	300	300
	NEEDED	DENT MEDIUM(80-160 mm)	354	N/A	384	384
		DENT LARGE(OVER 160 mm)	420	N/A	462	462
	TAIL GATE	SCUFF/SCRATCH SMALL < 100 mm	N/A	288	300	N/A
		SCUFF/SCRATCH MEDIUM(100-150 mm)	N/A	372	384	N/A
		SCUFF/SCRATCH LARGE(OVER 150 mm)	N/A	444	462	N/A
		DENT SMALL (UP TO 30 mm, NO PAINT DAMAGE)	N/A	114	114	N/A
		DENT SMALL(UP TO 80 mm)	N/A	288	300	N/A
		DENT MEDIUM(80-160 mm)	N/A	384	396	N/A
		DENT LARGE(OVER 160 mm)	N/A	564	588	N/A
		DAMAGE DUE TO OVER OPENING BY WIND	N/A	600	660	N/A
	REAR BUMPER	SCUFF/SCRATCH SMALL < 100 mm	264	288	300	348
		SCUFF/SCRATCH MEDIUM(100-150 mm)	354	372	384	384
		SCUFF/SCRATCH LARGE(OVER 150 mm)	420	444	462	462
		DENT SMALL(UP TO 80 mm)	264	288	300	300
		DENT MEDIUM(80-160 mm)	354	372	384	384
		DENT LARGE(OVER 160 mm)	420	444	462	462
		BUMPER REFLECTOR (L or R)	66	66	N/A	N/A
		BUMPER CORNER DAMAGE ONLY(L or R)	N/A	N/A	N/A	210
		CRACK SMALL (UP TO 100 mm)	372	372	384	420
		CRACK MEDIUM (100-150 mm)	408	408	432	528
		CRACK LARGE (OVER 150 mm)	468	468	528	612
	WINDOWS					
	WINDSCREEN	CHIP UNDER 25 mm	36	36	36	36
		CRACKED	252	540	444	252
	SIDE WINDOW	TRIANGLE SHAPE	144	144	168	180
		DOOR WINDOW (L/R)	192	192	204	210
		SLIDING DOOR WINDOW (L/R/)	N/A	690	252	N/A
		REAR QUARTER SIDE WINDOW (L/R)	N/A	330	534	N/A
		TAILGATE WINDOW	N/A	462	570	N/A
		REAR LEFT DOOR	198	N/A	210	N/A
		REAR RIGHT DOOR	180	N/A	210	N/A

TYRES			66	78	114	126
INTERIOR		COOKING KIT REPLACEMENT	120	150	150	240
		BURNT FLOOR	120	120	120	N/A
		MISSING AWNING	300	300	300	N/A
		MISSING AWNING POLE	24	24	24	N/A
		MISSING/BURNT MATTRESSES	300	300	300	504
		BURNT SEATS	540	540	540	540

MOTORHOME SPECIFIC DAMAGE PRICES

ITEM	DAMAGE TYPE	PRICE
WINDOWS		
	LARGE SIDE WINDOW	590
	OVERCAB SIDE WINDOW	395
	MEDIUM SIDE WINDOW	540
	BACK WINDOW	495
	SKYLIGHT GLASS	195
	SKYLIGHT COMPLETE	315
	OVERCAB PANORAMIC WINDOW	445
DOORS		
	GAS LOCKER DOOR	354
	GAS LOCKER DOOR FRAME	258
	HABITATION DOOR	834
	HABITATION DOOR FRAME	474
	TOILER OUTSIDE SERVICE FLAP	258
OUTSIDE		
	AERIAL	252
	WING MIRROR	366
	MIRROR CASE ONLY	114
	MIRROR GLASS ONLY	66
	WHEEL ARCH TRIM	264
	SIDE MARKER TOP	42
	SIDE MARKER BOTTOM	42
	CAB CORNER PANEL	594
	OVER 1.8M HIGH DAMAGE	INDIVIDUAL
INTERIOR		
	FREEVIEW TV	245
	TABLE(CRACK)	360
	BUNK BED DAMAGE	From 295
	HOB SAFETY GLASS	320
	OVEN SAFETY GLASS	315
	FRIDGE DOOR HANDLE	45
	EXCESSIVELY DIRTY/STAINED MATTRESS	90/mattress
	TOILETTE CASSETTE DIRTY	200
	EXCESSIVELY DIRTY VEHICLE CLEANING FEE	180